

# Product Change Notification

**Overview:** Please be advised that the following is notice of change to the FoamPro model 2002HP.

**Products Affected:** The following FoamPro 2002HP models have been discontinued:

- S105-2002HP
- S106-2002HP
- S205-2002HP

**Change Description:** Effective 8/13/2020, all FoamPro 2002HP models listed above have been discontinued.

**Reason for Change:** FRC is discontinuing the FoamPro 2002HP series due to the unavailability of the required subcomponents.

**Replacement Product:** FRC TurboFoam series, Model TFC121, High Pressure 2.1 GPM/600 PSI is an equivalent product to the FoamPro 2002HP in capacity, injection rate and pressure rating.

**References:** No references are applicable.

**Response:** No response to this notification is required. Requests for additional information should be directed to an FRC sales representative at 1.800.645.0074.